

Alpine Autohaus Ltd.



543 Bogart Lane
Grand Junction, CO 81505
(970) 248-8004
*** Preview Invoice ***

Repair Order #0024884

Original Estimate #0006010

1/11/2022

4:29 pm

2005 SAAB 9-5 ARC

2.3

VIN : YS3ED59A753521671

Mileage : In 187559 Out 187559

Trans : AUTO

License : TEMPWEBB

4WD : 521671

Unit # 521671

INPUT

Your Service Writer Today Is: COLTON DUBBEL

Center: RETAIL

Service Requests:

Replace clock spring and harness.

Category Summary

OTHER

Parts

\$0.00

Labor

\$260.00

Job Total

\$260.00

Technician	Service Description	Parts	Labor	Job Total
EG	Replace clockspring harness.		260.00	260.00

Services Recommended to Customer

Diagnose and replace oil pan gasket and change engine oil.

Diagnose and replace power steering reservoir, pressure hose and return

Parts Recommended To Customer

1	93 186 554	Oil Filter
1	510.031	Gasket Maker RTV Dir
4.5	2l	05W40 MOTUL FULLY SY
1	44 82 600	P/S Reservoir
1	12 766 940	P/S RETURN HOSE
1	BULK HOSE	P.S. HOSE
1	000 043 305 74	POWER STEERING FLUID

Repair Order Notes

WARRANTY INFORMATION

All other products and workmanship are warranted for 12 months or 12000 miles from the date of installation unless otherwise specified. All parts shown are new unless otherwise specified. I hereby authorize you and/or your agents to contact me regarding the products and services provided. An express mechanic's lien is hereby granted. I acknowledge receipt of a copy of this repair order.

Thank you for your business!

Questions or comments? Call us at 970-248-8004.

Visit us online at www.alpineautohaus.net

Customer Signature: _____

Date: _____

TOTAL PARTS	\$0.00
TOTAL LABOR	\$260.00
SUBLET	\$0.00
SHOP SUPPLY	\$15.60
SUBTOTAL	\$275.60
OTHER FEES	\$0.00
SALES TAX	\$1.33
REPAIR ORDER TOTAL	\$276.93
PAID	\$0.00
DUE	\$276.93

